

City College of San Francisco  
Facilities Department- Buildings & Grounds  
~~November~~ repair

- 10 Student Health - Exterior drains and wall repairs for water infiltration
- 11 MUB- Pavement marking
- 12 Science Hall- Stairwell roof drain leak
- 13 Creative Arts- Leak repair in classroom
- 14 Library- boiler replacement
- 15